



AFTERMARKET

LINKAGES AND SUSPENSION COMPONENTS



Version 1 | Valid from .2020



www.lemfoorderprecision.com

LEMFÖRDER





GENERAL INFORMATION



The products listed in this catalog must be installed in a workshop by qualified personnel only.

To fulfill your request, we need the complete order number, for example:

Tie Rod End	38747 01
Tie Rod Axle Joint	38837 01
Track Control Arm	38838 01


Clutch kit	3000 158 001
Clutch pressure plate	3082 168 231
Clutch disk	1862 403 031
Releaser	3151 816 001

In case of doubt, please provide the type description and the model year of the vehicle for which the desired item is intended.

This catalog is only an excerpt of our product range – our electronic media provide a complete overview.

www.zf.com/aftermarket/catalog

WebCat
Online catalog



InCat
Electronic catalog



E-Book



All rights reserved. Duplication or joint use of this catalog, even in extracts, for the creation of your own catalog is prohibited, unless explicit consent is given.

Replacement part numbers from the vehicle manufacturer serve only for purposes of comparison.

Use of such information in invoices to the vehicle owner is not permitted.

Current terms and conditions are available at www.zf.com/aftermarket/documents



INDEX

SR.NO.	OEM NAME	PRODUCT RANGE	BRAND	PAGE NO
1	MARUTI SUZUKI	STEERING & SUSPENSION	LF	3-11
2	MAHINDRA & MAHINDRA	STEERING & SUSPENSION	LF	12-16
3	TOYOTA MOTORS	STEERING & SUSPENSION	LF	17-24
4	TATA MOTORS	STEERING & SUSPENSION	LF	25-27
5	HYUNDAI	STEERING & SUSPENSION	LF	28-29
6	RENAULT NISSAN	STEERING & SUSPENSION	LF	30-32
7	FIAT/JEEP	STEERING & SUSPENSION	LF	32-33
8	FORD	STEERING & SUSPENSION	LF	33-34
9	VW/ SKODA	STEERING & SUSPENSION	LF	34-41
10	VW/ SKODA	CLUTCH KITS / RELEASER / SHOCK ABSORBERS / RTM	SACHS	42-47
11	HYUNDAI	CLUTCH KITS / RELEASER / SHOCK ABSORBERS / RTM	SACHS	48-50
12	RENAULT NISSAN	CLUTCH KITS / RELEASER / SHOCK ABSORBERS / RTM	SACHS	51-52
13	HONDA	CLUTCH KITS / RELEASER	SACHS	53-54
14	TOYOTA MOTORS	CLUTCH KITS / RELEASER	SACHS	55-56
15	MAHINDRA & MAHINDRA	CLUTCH KITS / CSC/ DMF	SACHS	57-59
16	MARUTI SUZUKI	CLUTCH KIT	SACHS	59
17	FORD	CLUTCH KITS / CSC / SHOCK ABSORBERS	SACHS	60-61
18	ASHOK LEYLAND	CLUTCH KIT	SACHS	62
19	MITSUBISHI	CLUTCH KIT	SACHS	62






**FOR REPAIR OF MARUTI SUZUKI
ALTO K10 (10/2010 – TILL NOW)**




ZF PART NO	PRODUCT	OE REF. NUMBER	IMAGE
38747 01 MRP: 286	Tie Rod End {Outer Ball Joint} (2 Pcs)	48810M84030	
38837 01 MRP:307	Tie Rod Axle Joint {Inner Ball Joint}	48830M70F00	
38838 01 MRP:551	Track Control Arm	45200M79F21	
38970 01 MRP:2120	Suspension Kit (set of 6 OBJ+IBJ+TCA)	99000M24120550	
38723 01 MRP: 704	Boot Set Pinion Side	48571M82000	
38724 01 MRP: 704	Boot Set Rack Side	48572M82000	



**FOR REPAIR OF MARUTI SUZUKI
A-STAR (10/2010 – TILL NOW)**




ZF PART NO	PRODUCT	OE REF. NUMBER	IMAGE
38725 01 MRP:998	Tie Rod End {Outer Ball Joint} (2 Pcs)	48810-61J00	
38726 01 MRP: 965	Tie Rod Axle Joint {Inner Ball Joint}	48830M68K00	
42233 01 MRP:1060	Stabilizer Link (2 Pcs)	42420M68K00	

**FOR REPAIR OF MARUTI SUZUKI
S-CROSS (04.2015-TILL NOW)
STABILIZER LINK: COMMON FOR SWIFT 2'ND GEN/ CIAZ /DZIRE 2'ND
GEN / SX4 / CELERIO**




ZF PART NO	PRODUCT	OE REF. NUMBER	IMAGE
38745 01 MRP: 1309	Tie Rod End {Outer Ball Joint } (2 Pcs)	48810M65M00	
38746 01 MRP: 1315	Tie Rod Axle Joint {Inner Ball Joint}	48830M65M00	
38719 01 MRP: 1004	Stabilizer Link (2 Pcs) COMMON FOR SWIFT 2'ND GEN/CIAZ/DZIRE 2'ND GEN / SX4	42420M60M02	



**FOR REPAIR OF MARUTI SUZUKI
CELERIO (12.2013-till Now)**

ZF PART NO	PRODUCT	OE REF. NUMBER	IMAGE
38744 01 MRP: 1028	Tie Rod End {Outer Ball Joint } (2 Pcs)	48810M65M00	
38726 01 MRP: 965	Tie Rod Axle Joint {Inner Ball Joint }	48830M65M00	
38719 01 MRP: 1004	Stabilizer Link (2 Pcs)	42420M60M02	

**FOR REPAIR OF MARUTI SUZUKI
EEO 1.2L (08.2010 - 05.2019)
VERSA 1.3L (01.2000 - 08.2010)**

ZF PART NO	PRODUCT	OE REF. NUMBER	IMAGE
38839 01 MRP: 735	Track Control Arm L	45202M83B00	
38840 01 MRP: 735	Track Control Arm R	45201M83B00	
43336 01 MRP: 1466	Control Arm Assembly (Set of 2 Pcs)	45202M83B00/ 45201M83B00	



FOR REPAIR OF MARUTI SUZUKI
WAGON R – 2'ND GEN (01.2010-12.2018)
STINGRAY 1.0L LXI (08.2013 - 02.2017)

ZF PART NO	PRODUCT	OE REF. NUMBER	IMAGE
42735 01 MRP: 354	Tie Rod End {Outer Ball Joint }	48810M67L00	
42908 01 MRP: 708	Tie Rod End {Outer Ball Joint } (Set of 2 Pcs)	48810M67L00	
42910 01 MRP: 403	Tie Rod Axle Joint {Inner Ball Joint }	48830M67L00	
42912 01 MRP: 787	Tie Rod Axle Joint {Inner Ball Joint } (Set of 2 Pcs)	48830M67L00	
42842 01 MRP: 1295	Control Arm Assembly R	45201M67L02	
42843 01 MRP: 1295	Control Arm Assembly L	45202M67L02	
43081 01 MRP: 2589	Control Arm Assembly (Set of 2 Pcs)	45201M67L02 /45202M67L02	



FOR REPAIR OF MARUTI SUZUKI
WAGONR (1'ST GEN) (01.2000-05.2006)
WAGONR (F/L 1'ST GEN) (06.2006-03.2010)

ZF PART NO	PRODUCT	OE REF. NUMBER	IMAGE
38747 01 MRP: 286	Tie Rod End {Outer Ball Joint }	48810M84030	
38837 01 MRP: 307	Tie Rod Axle Joint {Inner Ball Joint }	48830M70F00	
38844 01 MRP: 656	Track Control Arm	45200M79F11	
38969 01 MRP: 2535	Suspension Kit (set of 6 OBJ+IBJ+TCA)	99000M24120550	










**FOR REPAIR OF MARUTI SUZUKI
800 CAR (06.1986 - 01.2014)**

ZF PART NO	PRODUCT	OE REF. NUMBER	IMAGE
38742 01 MRP: 704	Boot Set Pinion Side	48571M82000	
38743 01 MRP: 704	Boot Set Rack Side	48572M82000	
38747 01 MRP: 286	Tie Rod End {Outer Ball Joint }	48810M84030	
38748 01 MRP: 313	Tie Rod Axle Joint {Inner Ball Joint }	48830M84030	
38838 01 MRP: 551	Track Control Arm	45200M50E30 / 45200- M50E41	



FOR REPAIR OF MARUTI SUZUKI
SWIFT 1'ST GEN (04.2005-07.2011)
RITZ 1'ST GEN (04.2009 - 07.2012)
DZIRE 1'ST GEN (03.2008 - 03.2012)

ZF PART NO	PRODUCT	OE REF. NUMBER	IMAGE
42734 01 MRP: 474	Tie Rod End {Outer Ball Joint }	48810M60J00	
42907 01 MRP: 951	Tie Rod End {Outer Ball Joint } (Set of 2 Pcs)	48810M60J00	
42909 01 MRP: 654	Tie Rod Axle Joint {Inner Ball Joint }	48830M63J00	
42911 01 MRP: 1060	Tie Rod Axle Joint {Inner Ball Joint } (Set of 2 Pcs)	48830M63J00	
42221 01 MRP: 1724	Control Arm Assy - R	45201M75J02	
42222 01 MRP: 1724	Control Arm Assy - L	45202M75J02	
42260 01 MRP: 3364	Control Arm Assy – L & R (Set of 2 Pcs)	45201M75J02 45202M75J02	
42236 01 MRP: 1038	Stabilizer Link (2 Pcs)	4240477A10	





FOR REPAIR OF MARUTI SUZUKI
SWIFT 2'ND GEN (07.2011-01.2016)
RITZ 2'ND GEN (07.2012-02.2017)
DZIRE 2'RD GEN (02.2012-02.2017)
ERTIGA 1'ST GEN (04.2012-11.2018)
CIAZ 1.3L/1.4L/1.5L (07.2014 – TILL NOW) – TIE ROD END (OBJ) ONLY




ZF PART NO	PRODUCT	OE REF. NUMBER	IMAGE
38720 01 MRP: 649	Tie Rod End R {Outer Ball Joint }	48820M74L00	
38721 01 MRP: 649	Tie Rod End L {Outer Ball Joint }	48820M74L10	
38722 01 MRP: 841	Tie Rod Axle Joint {Inner Ball Joint } (Set of 2 Pcs)	48830M74L00	
38831 01 MRP: 1981	Suspension Kit (2OBJ+2IBJ)	45201M74L20	
42223 01 MRP: 1891	Track Control Arm R	45201M74L20	
42224 01 MRP: 1891	Track Control Arm L	45202M74L20	
42261 01 MRP: 3562	Track Control Arm (Set of 2 Pcs)	45201M74L20 / 45202M74L20	



FOR REPAIR OF MARUTI SUZUKI
SWIFT 3'RD GEN (02.2018-TILL NOW)
DZIRE 3'RD GEN (03.2017-TILL NOW)
ERTIGA 2'ND GEN (12.2016-08.2019)
BALENO 2'ND GEN (11.2018- TILL NOW)
XL6 1.5L ZETA/ALPHA (08.2019-TILL NOW)

ZF PART NO	PRODUCT	OE REF. NUMBER	IMAGE
38718 01 MRP: 1033	Stabilizer Link (Set of 2 Pcs)	42420M68P00	
42731 01 MRP: 474	Tie Rod End {Outer Ball Joint }	48810M65M00	
42750 01 MRP: 609	Tie Rod Axle Joint {Inner Ball Joint } (FOR NEW SWIFT/NEW DZIRE ONLY)	48830M56R00	

FOR REPAIR OF MARUTI SUZUKI
VITARA BREEZA (02.2016-TILL NOW)

ZF PART NO	PRODUCT	OE REF. NUMBER	IMAGE
38745 01 MRP: 1309	Tie Rod End {Outer Ball Joint} (2 Pcs)	48810M65M00	
38746 01 MRP:1315	Tie Rod Axle Joint {Inner Ball Joint }	48830M65M00	
39326 01 MRP: 1356	Stabilizer Link (2 Pcs)	42420M60M02	



FOR REPAIR OF MAHINDRA & MAHINDRA
XUV 500 1ST GEN (10.2011-07.2015)
XUV 500 2ND GEN (07.2015-TILL NOW)

ZF PART NO	PRODUCT	OE REF. NUMBER	IMAGE
37409 01 MRP: 980	Tie Rod End L {Outer Ball Joint }	1102AAA01810N	
37410 01 MRP: 980	Tie Rod End R {Outer Ball Joint }	1102AAA01790N	
36793 01 MRP: 1144	Tie Rod Axle Joint {Inner Ball Joint } (Set of 2 Pcs)	1102ABC0003KT	
37412 01 MRP: 709	Stabilizer Link Front R	0401EA1021N	
37413 01 MRP: 716	Stabilizer Link Front L	0401EAA01151N	
42070 01 MRP: 1390	Stabilizer Link Front (Set of 2 Pcs)	-----	
37414 01 MRP: 1302	Stabilizer Link Rear (Set of 2 Pcs)	0402EA0481N	
42005 01 MRP: 2059	Rear Toe Link	0402BA2551N	
42006 01 MRP: `1413	Cross Axis Joint	-----	
37411 01 MRP: 858	Suspension Ball Joint	0401BA4141N	






FOR REPAIR OF MAHINDRA & MAHINDRA
MAHINDRA SCORPIO 3RD GEN (09.2014-11.2017)
MAHINDRA SCORPIO 3RD GEN F/L (12.2017-NOW)
TUV 300 1.5L T4/T6/T10 REFRESH DIESEL (09.2015-TILL NOW)

ZF PART NO	PRODUCT	OE REF. NUMBER	IMAGE
38201 01 MRP 1168	Tie Rod Axle Joint {Inner Ball Joint } (Set of 2 Pcs)	1102AAA01960N	
38202 01 MRP: 1168	Tie Rod End {Outer Ball Joint } (Set of 2 Pcs)	1102AAA01970N	
38332 01 MRP: 894	Lower Ball Joint	0401BAA08032N	
38333 01 MRP: 894	Upper Ball Joint	0401BAA08162N	
38832 01 MRP: 3593	Ball Joint Kit (Set of 4) {2 UBJ + 2 LBJ}	0401BAA08162N 0401BAA08032N	
38334 01 MRP: 704	Stabilizer Link L	0401EAA03012N	
38335 01 MRP: 704	Stabilizer Link R	0401EAA02592N	
38833 01 MRP: 1381	Stabilizer Link Front (Set of 2 Pcs)	0401EAA03012N 0401EAA02592N	



FOR REPAIR OF MAHINDRA & MAHINDRA
MAHINDRA SCORPIO 1ST GEN (10.2002-03.2008)
MAHINDRA SCORPIO 2ND GEN (04.2008-09.2014)
MAHINDRA THAR 2.5L GEN (07.2015-TILL NOW)

ZF PART NO	PRODUCT	OE REF. NUMBER	IMAGE
36822 01 MRP: 946	Tie Rod End {Outer Ball Joint } (Set of 2 Pcs)	1102AA0720N	
36823 01 MRP: 564	Tie Rod Axle Joint L {Inner Ball Joint }	1104AA0480N	
36824 01 MRP: 564	Tie Rod Axle Joint R {Inner Ball Joint }	1104AA0480N	





FOR REPAIR OF MAHINDRA & MAHINDRA
BOLERO 1ST GEN 2.5L BSII 2WD (03.2006 - 09.2011)
BOLERO 2ND GEN 2.5L PLUS (09.2011 – TILL NOW)
BOLERO 2ND GEN 1.5L POWER (09.2016 – TILL NOW)
BOLERO INVADER 2.5L GLX (03.2003-01.2010)




ZF PART NO	PRODUCT	OE REF. NUMBER	IMAGE
38475 01 MRP: 662	Tie Rod End {Outer Ball Joint }	1103AA0061N	
42904 01 MRP: 1207	Tie Rod End {Outer Ball Joint } (Set of 2 Pcs)	1102AAA02020N	
36825 01 MRP: 1243	Tie Rod Axle Joint {Inner Ball Joint }	1102AA0480N	
42815 01 MRP: 564	Stabilizer Link	0028990	
42906 01 MRP: 1061	Stabilizer Link (Set of 2 Pcs)	0028990	
42732 01 MRP: 864	Upper Ball Joint	0028910	
42733 01 MRP:789	Lower Ball Joint	0028923	
42905 01 MRP: 3021	Ball Joint Kit (Set of 4) {2 UBJ + 2 LBJ}	0028910 / 0028923	



**FOR REPAIR OF MAHINDRA & MAHINDRA
MAHINDRA MAXXIMO MINI VAN 0.9L (04.2011 – TILL NOW)**

ZF PART NO	PRODUCT	OE REF. NUMBER	IMAGE
36819 01 MRP: 1797	Track control arm L	0401BA3540N	
36820 01 MRP: 1797	Track control arm R	0401BA3541N	

**FOR REPAIR OF MAHINDRA & MAHINDRA
MARAZZO 1.5L DIESEL (09.2018-NOW)**

ZF PART NO	PRODUCT	OE REF. NUMBER	IMAGE
42730 01 MRP: 985	Stabilizer Link (L/R)	0401EBB00191N	
42729 01 MRP: 1103	Upper Ball Joint	0401BBB00111N	
42728 01 MRP: 967	Lower Ball Joint	0401BBB00561N	



FOR REPAIR OF TOYOTA MOTORS







INNOVA 1ST GEN 2.0L BSIII (02.2005 - 01.2012)
INNOVA 1ST GEN 2.5L BSIII (02.2005 - 01.2012)
INNOVA 1ST GEN 2.5L BSIV (04.2010 - 01.2012)
INNOVA 1ST GEN F/L 2.0L DLX (01.2012 - 03.2016)
INNOVA 1ST GEN F/L 2.5 DLX (01.2012 - 03.2016)

ZF PART NO	PRODUCT	OE REF. NUMBER	IMAGE
43142 01 MRP: 756	Tie Rod End {Outer Ball Joint }	45046-09320	
43147 01 MRP: 1512	Tie Rod End {Outer Ball Joint } (Set of 2 Pcs)	45046-09320	
43143 01 MRP: 778	Tie Rod Axle Joint {Inner Ball Joint }	4550309350	
43148 01 MRP: 1555	Tie Rod Axle Joint {Inner Ball Joint } (Set of 2 Pcs)	4550309350	
43144 01 MRP: 777	Upper Ball Joint	43310-09040	
43145 01 MRP: 1016	Lower Ball Joint	43330-09500	
43149 01 MRP: 3561	Ball Joint Kit (Set of 4 Pcs)	43310-09040 43330-09500	



FOR REPAIR OF TOYOTA MOTORS

INNOVA 1ST GEN 2.0L BSIII (02.2005 - 01.2012)
INNOVA 1ST GEN 2.5L BSIII (02.2005 - 01.2012)
INNOVA 1ST GEN 2.5L BSIV (04.2010 - 01.2012)
INNOVA 1ST GEN F/L 2.0L DLX (01.2012 - 03.2016)
INNOVA 1ST GEN F/L 2.5 DLX (01.2012 - 03.2016)

ZF PART NO	PRODUCT	OE REF. NUMBER	IMAGE
43094 01 MRP: 3625	Suspension Bush Front Kit (Set of 18 Pcs.)	-----	
43082 01 MRP: 3312	Suspension Bush Front Kit (Set of 8 Pcs.)	-----	
43100 01 MRP: 4051	Suspension Bush Rear Kit (Set of 13 Pcs.)	-----	
43083 01 MRP: 3412	Suspension Bush Rear Kit (Set of 8 Pcs.)	-----	
43167 01 MRP: 657	Stabilizer Link	488200K020	
43173 01 MRP: 1249	Stabilizer Link (Set of 2 Pcs.)	488200K020	









FOR REPAIR OF TOYOTA MOTORS
INNOVA CRYSTA 2ND GEN 2.4L (04.2016 – TILL NOW)
INNOVA CRYSTA 2ND GEN 2.7L (04.2016 – TILL NOW)
INNOVA CRYSTA 2ND GEN 2.8L (04.2016 – TILL NOW)

ZF PART NO	PRODUCT	OE REF. NUMBER	IMAGE
43146 01 MRP: 729	Tie Rod End {Outer Ball Joint }	45046-09830	
43150 01 MRP: 1712	Tie Rod End {Outer Ball Joint } (Set of 2 Pcs)	45046-09830	
43143 01 MRP: 778	Tie Rod Axle Joint {Inner Ball Joint }	4550309350	
43148 01 MRP: 1555	Tie Rod Axle Joint {Inner Ball Joint } (Set of 2 Pcs)	4550309350	
43144 01 MRP: 777	Upper Ball Joint	43310-09040	
43145 01 MRP: 1016	Lower Ball Joint	43330-09500	
43149 01 MRP: 3561	Ball Joint Kit (Set of 4 Pcs)	43310-09040 43330-09500	




FOR REPAIR OF TOYOTA MOTORS
INNOVA CRYSTA 2ND GEN 2.4L (04.2016 – TILL NOW)
INNOVA CRYSTA 2ND GEN 2.7L (04.2016 – TILL NOW)
INNOVA CRYSTA 2ND GEN 2.8L (04.2016 – TILL NOW)

ZF PART NO	PRODUCT	OE REF. NUMBER	IMAGE
43094 01 MRP: 3625	Suspension Bush Front Kit (Set of 18 Pcs.)	-----	
43082 01 MRP:3312	Suspension Bush Front Kit (Set of 8 Pcs.)	-----	
43100 01 MRP: 4051	Suspension Bush Rear Kit (Set of 13 Pcs.)	-----	
43083 01 MRP: 3412	Suspension Bush Rear Kit (Set of 8 Pcs.)	-----	
43167 01 MRP: 657	Stabilizer Link	488200K020	
43173 01 MRP: 1249	Stabilizer Link (Set of 2 Pcs.)	488200K020	



FOR REPAIR OF TOYOTA MOTORS

FORTUNER 1ST GEN F/L 3.0 SR 2WD 5AT (01.2012 - 11.2016)
FORTUNER 1ST GEN 3.0 SR 4WD (08.2009 - 12.2011)
FORTUNER 1ST GEN F/L 3.0 SR 2WD MT (01.2012 - 11.2016)
FORTUNER 1ST GEN F/L 3.0 SR 2WD 4AT (01.2012 - 11.2016)
FORTUNER 1ST GEN F/L 2.5 SR 2WD MT (01.2015 - 11.2016)
FORTUNER 1ST GEN F/L 3.0 SR 4WD AT (01.2015 - 11.2016)
FORTUNER 1ST GEN F/L 2.5 SR 2WD AT (01.2015 - 11.2016)

ZF PART NO	PRODUCT	OE REF. NUMBER	IMAGE
36453 01 MRP:1396	Tie Rod End {Outer Ball Joint }	45046-09280	
43164 01 MRP:1249	Stabilizer Link-R	48820-0K030 48810-0K030	
43165 01 MRP: 1249	Stabilizer Link-L	48820-0K060 48810-0K010	
43171 01 MRP: 2378	Stabilizer Link (Set of 2 Pcs.)	Same as Above	
43143 01 MRP: 778	Tie Rod Axle Joint {Inner Ball Joint }	4550309350 4550309321	
43148 01 MRP: 1555	Tie Rod Axle Joint {Inner Ball Joint } (Set of 2 Pcs)	4550309350 4550309321	



FOR REPAIR OF TOYOTA MOTORS




FORTUNER 2ND GEN (10.2016-TILL NOW)
FORTUNER 2ND GEN 2.7L M(10.2016 - TILL NOW)
FORTUNER 2ND GEN 2.8L H (10.2016 - TILL NOW)
FORTUNER 2ND GEN 2.7L H AT (10.2016 - TILL NOW)
FORTUNER 2ND GEN 2.8L H 5AT (10.2016 - TILL NOW)
FORTUNER 2ND GEN 2.8L M(10.2016 - TILL NOW)
FORTUNER 2ND GEN 2.8L H 6AT (10.2016 - TILL NOW)

ZF PART NO	PRODUCT	OE REF. NUMBER	IMAGE
43163 01 MRP: 1063	Tie Rod End {Outer Ball Joint }	45046-09850	
43170 01 MRP: 2021	Tie Rod End {Outer Ball Joint } (Set of 2 Pcs)	45046-09850	
43164 01 MRP: 1249	Stabilizer Link-R	48820-0K030 48810-0K030	
43165 01 MRP:1249	Stabilizer Link-L	48820-0K060 48810-0K010	
43171 01 MRP: 2378	Stabilizer Link (Set of 2 Pcs.)	Same as Above	



FOR REPAIR OF TOYOTA MOTORS

LAND CRUISER PRADO J120 4.0 GX AT (09.2002 - 08.2004)
LAND CRUISER PRADO J120 3.0 GX AT (09.2002 - 08.2004)
LAND CRUISER PRADO J120 3.0 GX MT (09.2002 - 08.2004)
LAND CRUISER PRADO J120 3.0 GX AT (08.2004 - 08.2009)
LAND CRUISER PRADO J120 4.0 GX AT (08.2004 - 08.2009)
LAND CRUISER PRADO J120 3.0 GX MT (08.2004 - 08.2009)
LAND CRUISER PRADO J150 3.0 (12.2009 - 12.2013)
LAND CRUISER PRADO J150 F/L 3.0 AT (12.2013 – TILL NOW)

ZF PART NO	PRODUCT	OE REF. NUMBER	IMAGE
43164 01 MRP: 1249	Stabilizer Link-R	48820-0K030 48810-0K030	
43165 01 MRP:1249	Stabilizer Link-L	48820-0K060 48810-0K010	
43171 01 MRP: 2378	Stabilizer Link (Set of 2 Pcs.)	Same as Above	



FOR REPAIR OF TOYOTA MOTORS

COROLLA ALTIS 1.8 J MT (08.2008 – TILL NOW)

COROLLA ALTIS 1.4 G MT (08.2008 – TILL NOW)

COROLLA ALTIS 1.4 GL MT (08.2008 – TILL NOW)

COROLLA ALTIS 1.8 G MT (08.2008 – TILL NOW)

COROLLA ALTIS 1.8 GL MT (08.2008 – TILL NOW)

COROLLA ALTIS 1.8 G AT (08.2008 – TILL NOW)

ZF PART NO	PRODUCT	OE REF. NUMBER	IMAGE
43169 01 MRP: 785	Tie Rod End {Outer Ball Joint }	45046-19425 45046-09620	
43175 01 MRP: 1570	Tie Rod End {Outer Ball Joint } (Set of 2 Pcs)	45046-19425 45046-09620	
43168 01 MRP: 738	Stabilizer Link	48820-47010	
43174 01 MRP: 1593	Stabilizer Link (Set of 2 Pcs.)	48820-47010	



FOR REPAIR OF TATA MOTORS

TATA ARIA (10.2010-04.2014)

TATA ARIA LET (05.2014-04.2017)

TATA HEXA 2.2L (01.2017 – TILL NOW)

TATA HARRIER 2.0L XT (01.2019 – TILL NOW)

TATA SAFARI STORME LET 2.2L (06.2015 – TILL NOW)


ZF PART NO	PRODUCT	OE REF. NUMBER	IMAGE
36764 01 MRP: 943	Ball Joint Lower (Set of 2 Pcs)	269932100190	
36767 01 MRP: 940	Ball Joint Upper (Set of 2 Pcs)	287032110151	
39553 01 MRP: 3220	Ball Joint Kit (Set of 4 Pcs)	885528700005	
36780 01 MRP: 463	Stabilizer Link RR (Set of 2 Pcs)	287032900115	
36781 01 MRP: 595	Stabilizer Link FR (Left)	287032800117	
36782 01 MRP: 595	Stabilizer Link FR (Right)	287032800116	



FOR REPAIR OF TATA MOTORS
TATA SUMO 2.0 L (01.94-06.2019)
SUMO GOLD 3.0 L (02.2012-10.2019)
SUMO GRANDE 2.2 L (01.2008-06.2014)
SUMO VICTA 3.0 L (04.2007-05.2011)

ZF PART NO	PRODUCT	OE REF. NUMBER	IMAGE
36763 01 MRP: 718	Ball Joint Upper (Set of 2 Pcs)	269932100194	
36765 01 MRP: 741	Ball Joint Lower (Set of 2 Pcs)	265433200133	
36788 01 MRP: 1240	Tie Rod Axle Joint {Inner Ball Joint } Assly	282346600124	
36789 01 MRP: 572	Tie Rod End L {Outer Ball Joint }	282346600151	
36790 01 MRP: 572	Tie Rod End R {Outer Ball Joint }	282346600151	

FOR REPAIR OF TATA MOTORS
TATA INDICA (06.2001-TILL NOW)

ZF PART NO	PRODUCT	OE REF. NUMBER	IMAGE
36772 01 MRP: 459	Ball Joint Lower	284332100136	



FOR REPAIR OF TATA MOTORS
TATA TIAGO (04.2016-TILL NOW)
TATA TIGOR (03.2017-TILL NOW)




ZF PART NO	PRODUCT	OE REF. NUMBER	IMAGE
42751 01 MRP: 595	Ball Joint Lower	542732990101	
42219 01 MRP: 3929	Track Control Arm R	542432100123	
42255 01 MRP: 3936	Track Control Arm L	542432100122	
42257 01 MRP:7659	Track control Arm Kit (Set of 2 Pcs)	542432100122 /542432100123	



FOR REPAIR OF HYUNDAI

i10 1'ST GEN (09.2007-07.2010)


i10 1ST GEN F/L 1.1L (08.2010 - 08.2013)

ZF PART NO	PRODUCT	OE REF. NUMBER	IMAGE
37407 01 MRP: 842	Tie Rod Axle Joint {Inner Ball Joint } (Set of 2 Pcs)	57724-0X000	
37408 01 MRP: 823	Tie Rod End {Outer Ball Joint } (Set of 2 Pcs)	56820-0X000	
42234 01 MRP: 1038	Stabiliser Link (Set of 2 Pcs)	54830-0X501	

FOR REPAIR OF HYUNDAI

i20 1'ST GEN (10.2008-03.2012)

i20 1ST GEN F/L 1.1L (03.2012 - 07.2014)

ZF PART NO	PRODUCT	OE REF. NUMBER	IMAGE
42235 01 MRP:1016	Stabiliser Link (Set of 2 Pcs)	548301J000 548401J000	





FOR REPAIR OF HYUNDAI

GRAND i10 1.2L (08.2013 - 11.2016)
GRAND i10 F/L 1.2L (12.2016 - TILL NOW)
XCENT 1.2L (08.2013 - 11.2016)
XCENT F/L 1.2L (12.2016 - TILL NOW)

ZF PART NO	PRODUCT	OE REF. NUMBER	IMAGE
38394 01 MRP: 1352	Tie Rod Axle Joint {Inner Ball Joint } (Set of 2 Pcs)	56540B4000	
43335 01 MRP: 1540	Tie Rod End {Outer Ball Joint } (Set of 2 Pcs)	56820B4000 56821B4050	
38390 01 MRP: 749	Tie Rod End L {Outer Ball Joint }	56820B4000	
38391 01 MRP: 749	Tie Rod End R {Outer Ball Joint }	56821B4050	

FOR REPAIR OF HYUNDAI

SANTRO 1ST GEN 1.0L (09.1998 - 05.2003)
SANTRO XING 2ND GEN 1.1L (05.2003 - 10.2014)

ZF PART NO	PRODUCT	OE REF. NUMBER	IMAGE
36829 01 MRP: 442	Tie Rod End {Outer Ball Joint }	5682002500	
36830 01 MRP: 439	Tie Rod Axle Joint {Inner Ball Joint }	5775502000	






FOR REPAIR OF RENAULT / NISSAN
PULSE (01.2012 – TILL NOW)
SCALA (01.2012 – TILL NOW)
NISSAN MICRA ACTIVE (04.2013 – TILL NOW)
NISSAN SUNNY (N17K) 1.5 (09.2011 – TILL NOW)
DATSUN GO / REDI GO (03.2014 – TILL NOW)

ZF PART NO	PRODUCT	OE REF. NUMBER	IMAGE
36829 01 MRP:442	Stabilizer Link (Set of 2pc)	54618JX00A	
39823 01 MRP: 1004	Tie Rod Axle Joint {Inner Ball Joint }	D85211HA0A	
39824 01 MRP: 815	Tie Rod End R {Outer Ball Joint }	D86401HA0A	
39825 01 MRP: 815	Tie Rod End L {Outer Ball Joint }	D85201HA0A	
42229 01 MRP: 1141	Suspension Ball Joint (Set of 2pc)	40160-50Y00	




FOR REPAIR OF RENAULT / NISSAN
PULSE (01.2012 – TILL NOW)
SCALA (01.2012 – TILL NOW)
NISSAN MICRA ACTIVE (04.2013 – TILL NOW)
NISSAN SUNNY (N17K) 1.5 (09.2011 – TILL NOW)


ZF PART NO	PRODUCT	OE REF. NUMBER	IMAGE
43341 01 MRP: 2403	Control Arm -Left	545011HA5A 54501-1HA0C 54501-1HA5D 54501-1HA6A	
43342 01 MRP: 2403	Control Arm -Left	545001HA5A 54500-1HA0C 54500-1HA5D 54500-1HA6A	
43343 01 MRP: 4693	Control Arm -Kit	-----	




FOR REPAIR OF RENAULT / NISSAN
KWID (06.2009– 01.2014)
REDI-GO (06.2009– 01.2014)

ZF PART NO	PRODUCT	OE REF. NUMBER	IMAGE
42228 01 MRP: 1096	Suspension Ball Joint	401606961R	

FOR REPAIR OF RENAULT / NISSAN
DUSTER 1.6L HSA8 PETROL {01.2012 - 06.2017}
DUSTER 1.5L HSMW DIESEL {01.2012 - 06.2017}
TERRANO 1.5 XE / XL PLUS DIESEL {09.2013 – TILL NOW}
TERRANO 1.5 XV PREMIUM DIESEL {09.2013 - TILL NOW}
TERRANO 1.6 XL PETROL {09.2013 – TILL NOW}

ZF PART NO	PRODUCT	OE REF. NUMBER	IMAGE
42231 01 MRP: 1469	Stabilizer Link (Set of 2pc)	551103022R	

FOR REPAIR OF FIAT
GRAND PUNTO 1.2 (06.2009– 01.2014)
GRAND PUNTO 1.3 (06.2009– 01.2014)
GRAND PUNTO 1.3 (06.2009– 01.2014)
LINEA 1.3 (01.2009 – 07.2014)
LINEA 1.4 (01.2009 – 07.2014)

ZF PART NO	PRODUCT	OE REF. NUMBER	IMAGE
36794 01 MRP: 548	Tie Rod End {Outer Ball Joint} RH	G0805005 59116377	
36795 01 MRP: 548	Tie Rod End {Outer Ball Joint} LH	G0805004 59116377	
36796 01 MRP: 512	Tie Rod Axle Joint {Inner Ball Joint } RH/LH	G0805003 59116378 59116379	




FOR REPAIR OF JEEP

COMPASS 2.0 2L MULTIJET II (DIESEL) (07.2017 – TILL NOW)
COMPASS 2.0 4x4 2L MULTIJET II (DIESEL) (07.2017 – TILL NOW)
COMPASS 1.4L MULTIAIR PETROL (07.2017 – TILL NOW)

ZF PART NO	PRODUCT	OE REF. NUMBER	IMAGE
42725 01 MRP: 782	Tie Rod End {Outer Ball Joint} LH	68351149AA	
42726 01 MRP: 782	Tie Rod End {Outer Ball Joint} RH	68351148AA	
42727 01 MRP: 672	Tie Rod Axle Joint {Inner Ball Joint } RH/LH	68066486AA 68040224AB	
42232 01 MRP: 1337	Lower Ball Joint Front Axle, Left and right	68246489AA	

FOR REPAIR OF FORD

IKON 1.3L PETROL (01.1999 - 12.2011)
IKON 4DR 1.4L (DIESEL) (01.2003-12.2011)

ZF PART NO	PRODUCT	OE REF. NUMBER	IMAGE
36791 01 MRP: 661	Lower Ball Joint (Front Axle Left and right)	-----	





FOR REPAIR OF FORD

FIESTA 1ST GEN 1.4L (04.2005 - 12.2007)

FIESTA 1ST GEN 1.6L (04.2005 - 12.2007)

FIGO 1ST GEN 1.2L (03.2010 - 07.2015)

FIGO 1ST GEN 1.4L (03.2010 - 07.2015)

ZF PART NO	PRODUCT	OE REF. NUMBER	IMAGE
36792 01 MRP: 651	Suspension Ball Joint	AS69-3395AA	
42227 01 MRP: 1496	Stabilizer Link (Set of 2 pc)- Applicable for EcoSport also	6N293B438-AA	

FOR REPAIR OF VW / SKODA

FABIA 1.2L (01.2008- 05.2013)

RAPID 1.5 L (10.2011- 08.2016)

AMEO (06.2016 – TILL NOW)

POLO (08.2009- TILL NOW)

VENTO (08.2010- TILL NOW)

ZF PART NO	PRODUCT	OE REF. NUMBER	IMAGE
25463 01 MRP: 1778	Stabilizer Link	6R0411315	
33905 01 MRP: 2106	Suspension Ball Joint	6R0407365B	
33906 01 MRP: 2106	Suspension Ball Joint	6R0407365B	
26669 02 MRP: 1739	Tie Rod End L {Outer Ball Joint }	6RD423811B	
26670 02 MRP: 1739	Tie Rod End R {Outer Ball Joint }	6RD423812B	



FOR REPAIR OF VW / SKODA

FABIA 1.2L (01.2008- 05.2013)

RAPID 1.5 L (10.2011- 08.2016)

AMEO (06.2016 – TILL NOW)

POLO (08.2009- TILL NOW)

VENTO (08.2010- TILL NOW)

ZF PART NO	PRODUCT	OE REF. NUMBER	IMAGE
35990 02 MRP:	Tie Rod Axle Joint {Inner Ball Joint }	6RU423810	
37238 01 MRP:	Track Control Arm L	6R0407151F	
37239 01 MRP:	Track Control Arm R	6R0407151F	
20390 01 MRP: 633	Protective Cap/Bellow, shock absorber	357413175A	
21027 01 MRP: 765	Rubber Buffer, suspension	357412303F	
21793 02 MRP: 845	Top Strut Mounting	1J0412331	
10203 02 MRP: 337	Control Arm/Trailing Arm Bush-Fr Axle Left & Right	191407182	
21113 01 MRP: 718	Control Arm/Trailing Arm Bush Front Axle, Left and right, Rear for control arm	1J0407181	



FOR REPAIR OF VW / SKODA

OCTAVIA (04.1999- 12.2010)

BEETLE (01.1998 - 04.2019)

ZF PART NO	PRODUCT	OE REF. NUMBER	IMAGE
35281 02 MRP: 2911	Tie Rod End L {Outer Ball Joint }	1K0423811K	
35282 02 MRP: 2911	Tie Rod End R {Outer Ball Joint }	6R0407151F	
38181 01 MRP:	Stabilizer Link	1J0411315K	
21855 02 MRP: 3523	Rod Assembly Front Axle, Left	1J0422803B	
21856 02 MRP: 3523	Rod Assembly Front Axle, Right	1J0422804H	
22250 02 MRP: 1662	Tie Rod Axle Joint {Inner Ball Joint} / Axial Rod Front Axle, Left & Right	1J0422803B	
21699 01 MRP:	Stabilizer link-Fr Axle Left & Right	1J0411315J	
22475 03 MRP: 4654	Control Arm Front Axle, Left and right	1J0407151A	










ZF PART NO	PRODUCT	OE REF. NUMBER	IMAGE
17619 02 MRP: 2011	Suspension Ball Joint - Front Axle, Lower, Left	1J0407365A	
17620 02 MRP: 2011	Suspension Ball Joint - Front Axle, Lower, Right	1J0407366A	
35269 01 MRP: 1392	Top Strut Mounting Rear Axle, Left and right	1K0423811K	
22613 01 MRP: 739	Rubber Buffer, suspension Rear Axle, Left & Right	1J0512131B	
20390 01 MRP: 633	Protective Cap/Bellow, shock absorber Front Axle, Left and right	357413175A	
17636 02 MRP:485	Anti-Friction Bearing, suspension strut support mounting	1J0412249	
21236 01 MRP:1249	Mounting, axle beam, Rear Axle, Left and right	1J0501541C	
10203 02 MRP: 337	Control Arm/Trailing Arm Bush- Front Axle, Left and right,	191407182	
21113 01 MRP: 718	Control Arm/Trailing Arm Bush Front Axle, Left and right, Rear for control arm	1J0407181	



FOR REPAIR OF VW / SKODA

LAURA (02.2004- 12.2013)
SUPERB (03.2008- 03.2016)
JETTA (10.2005- 10.2010)
PASSAT (08.2010-10.2019)
AUDI A3 (04.2008-12.2012)

ZF PART NO	PRODUCT	OE REF. NUMBER	IMAGE
35281 02 MRP: 2911	Tie Rod End L {Outer Ball Joint }	1K0423811K	
35282 02 MRP: 2911	Tie Rod End R {Outer Ball Joint }	6R0407151F	
26774 01 MRP: 2632	Stabiliser Link Front Axle, Left & Right	1K0411315J	
26775 02 MRP: 2459	Stabiliser Link Rear Axle, Left & Right	1K0505465J	
33834 01 MRP: 6874	Track Control Arm, Front Axle, Left	1K0407151AC	
33835 01 MRP: 6874	Track Control Arm, Front Axle, Right	1K0407151AC	
25329 02 MRP: 2429	Tie Rod Axle Joint {Inner Ball Joint } / Front Axle, Left & Right	1K0423810A	



ZF PART NO	PRODUCT	OE REF. NUMBER	IMAGE
26772 02 MRP: 2653	Suspension Ball Joint - Front Axle, Lower, Left	1J0407365A	
26773 02 MRP: 2653	Suspension Ball Joint - Front Axle, Lower, Right	1J0407366A	
29916 01 MRP: 737	Control Arm/Trailing Arm Bush- Front Axle, Left and right,	1K0407182	
35725 01 MRP: 1102	Control Arm/Trailing Arm Bush Front Axle, Left and right, Rear for control arm	1K0407183M	
27184 01 MRP: 2133	Top Strut Mounting Front Axle, Left and right	1K0412331B	
33144 01 MRP: 5085	Engine Mounting Hydro Bearing Fitting Position: Left	1K0199555Q	
33142 01 MRP: 4695	Engine Mounting Hydro Bearing Fitting Position: Left	357413175A	
27070 01 MRP: 7876	Engine Mounting Hydro Bearing Fitting Position: Right	1K0199262AS	
33147 01 MRP: 1533	Engine Mounting Fitting Position: Lower	1K0199867A	



ZF PART NO	PRODUCT	OE REF. NUMBER	IMAGE
33150 01 MRP: 1736	Engine Mounting Fitting Position: Upper	1K0199868A	
31764 01 MRP: 1367	Anti- Friction Bearing, Front Axle, Left and right	1K0412249B	
29917 01 MRP: 647	Control Arm/Trailing Arm Bush, Rear Axle, Lower, Left and right, inner, at spring bracket	1K0505171C	
29918 01 MRP: 557	Control Arm-/Trailing Arm Bush, Rear Axle, Upper, Left and right, Outer	1K0505203A	
29919 01 MRP: 582	Control Arm/Trailing Arm Bush, Rear Axle, Upper, Left and right, inner	1K0505279A	
27306 01 MRP: 674	Control Arm-/Trailing Arm Bush; Rear Axle, Left and right, Rear, Lower, Outer, at spring bracket	1K0505553A	
38620 01 MRP:	Control Arm-/Trailing Arm Bush; Rear Axle, Left and right	1K0505541B	



ZF PART NO	PRODUCT	OE REF. NUMBER	IMAGE
29921 01 MRP: 670	Mounting, track rod Rear Axle, Upper, Left and right, Outer	1K0505543A	
29314 01 MRP: 611	Mounting, track rod Rear Axle, Upper, Left and right, inner	1K0501541C	
34763 01 MRP: 1992	Control Arm-/Trailing Arm Bush; Front Axle, Right, Rear	1K0199232G	
34762 01 MRP: 1992	Control Arm-/Trailing Arm Bush; Front Axle, Left, Rear	1K0199231G	



FOR REPAIR OF VW / SKODA
LAURA 1.9L TDI (06.2004- 12.2010)
JETTA 1.9L TDI (08.2005- 10.2010)

ZF PART NO	PRODUCT	OE REF. NUMBER	IMAGE
3000 970 036 MRP: 14025	Clutch Kit with releaser 5-Speed Manual Transmission Model year Before: 12/2010 Diameter [mm]: 228 Hub Profile: 20.3x22.1-28N Number of Teeth: 28	03L 141 016 B	
2290 602 004 MRP: 36110	Clutch Kit ZMS Modul XTend 5-Speed Manual Transmission Model year Before: 12/2010 SACHS-version Diameter [mm]: 228 Number of Teeth: 28 Contains twin-mass flywheel, clutch cover assembly, clutch disc and releaser includes bolt for pressure plate and flywheel mounting	03L 141 016 B	
2290 601 050 MRP: 36110	Clutch Kit ZMS Modul XTend 5-Speed Manual Transmission; Model year from : 11/2009 SACHS-version; Dia [mm]: 228 Number of Teeth: 28		
3151 000 388 MRP: 1477	Clutch Releaser	02A 141 165 M	
6284 000 056 MRP: 3736	Master Cylinder, clutch	1K0 721 388 A	
6283 000 047 MRP: 2799	Slave Cylinder, clutch	1K0 721 261 A	



ZF PART NO	PRODUCT	OE REF. NUMBER	IMAGE
312 267 MRP: 7165	Front Shock Absorber- Manual for vehicles with std. chassis Suspension Strut Twin-Tube Gas Pressure Housing Diameter: 50 mm	1K0 413 031 AD	
317 572 MRP: 7025	Front Shock Absorber - Twin-Tube Gas Pressure Parameter: SFE36/25X156A Housing Diameter: 55 mm	1T0 413 031 CK	
310 950 MRP: 5858	Rear Shock Absorber Gas Pressure Twin-Tube	03L 141 016 B	
802 321 MRP:	Top Strut Mounting Fitting Position: Front Axle, Left and right without ball bearing	1K0 412 331 B	
801 038 MRP: 1213	Anti-Friction Bearing, suspension strut support mounting. Front Axle, Left and right	1K0 412 249 B	
900 105 MRP: 2032	Dust Cover Kit, shock absorber Service Kit Fitting Position: Front Axle for vehicles with sports suspension	00 1770 900 105	
900 119 MRP: 1939	Dust Cover Kit, shock absorber Service Kit Fitting Position: Rear Axle for vehicles with standard chassis	00 1770 900 119	



FOR REPAIR OF VW / SKODA
LAURA 2.0 TDI (02.2004-12.2013)
SUPERB 2.0 TDI (01.2009- 03.2016)
YETI 2.0 TDI (11.2009- TILL NOW)
PASSAT 2.0 TDI (08.2010- 08.2019)
AUDI A3 2.0 TDI (04.2008-12.2012)




ZF PART NO	PRODUCT	OE REF. NUMBER	IMAGE
3000 990 328 MRP:	Clutch Kit XTend Kit +CSC Engine Code: CFHF 6-Speed Manual Transmission Model year After: 11/2009 Diameter [mm]: 240 Number of Teeth: 23		
2294 001 361 MRP: 32103	Dual-mass Flywheel Engine Code: CFHF Diameter [mm]: 240 includes bolt for flywheel mounting	03L 105 266 CA	
3000 970 062 MRP: 20171	Clutch Kit XTend Engine Code: CFHF Diameter [mm]: 240 Hub Profile: 21.8x24.3-23N Number of Teeth: 23		
3182 600 241 MRP:	Central Slave Cylinder, clutch Engine Code: CFHF	0A5 141 671 S	
6284 000 056 MRP: 3736	Master Cylinder, clutch	1K0 721 388 A	
6283 000 047 MRP: 2799	Slave Cylinder, clutch	1K0 721 261 A	




ZF PART NO	PRODUCT	OE REF. NUMBER	IMAGE
312 267 MRP: 7165	Front Shock Absorber- Manual for vehicles with std. chassis Suspension Strut Twin-Tube Gas Pressure Housing Diameter: 50 mm	1K0 413 031 AD	
317 572 MRP: 7025	Front Shock Absorber - Twin-Tube Gas Pressure Parameter: SFE36/25X156A Housing Diameter: 55 mm	1T0 413 031 CK	
310 950 MRP: 5858	Rear Shock Absorber Gas Pressure Twin-Tube	03L 141 016 B	
802 321	Top Strut Mounting Fitting Position: Front Axle, Left and right without ball bearing	1K0 412 331 B	
801 038	Anti-Friction Bearing, suspension strut support mounting. Front Axle, Left and right	1K0 412 249 B	
900 105	Dust Cover Kit, shock absorber Service Kit Fitting Position: Front Axle for vehicles with sports suspension	00 1770 900 105	
900 119	Dust Cover Kit, shock absorber Service Kit Fitting Position: Rear Axle for vehicles with standard chassis	00 1770 900 119	



FOR REPAIR OF VW / SKODA
POLO 1.2L PETROL (06.2009-08.2019)
FABIA 1.2L PETROL (01.2008-05.2013)
AMEO 1.2L MPI PETROL (06.2016-02.2018)

ZF PART NO	PRODUCT	OE REF. NUMBER	IMAGE
3000 954 585 MRP: 6562	Clutch Kit Diameter [mm]: 190 Number of Teeth: 28 With Releaser	03D141025C 03D141031A 02T141170B	
6284 000 032 6284 654 007 MRP: 2384	Master Cylinder, clutch	6Q0 721 388 C	
6283 005 802 MRP: 3342	Slave Cylinder, clutch	5Q0 721 261 D	

FOR REPAIR OF VW / SKODA
RAPID (NA2) 1.5 L TDi (10.2011- 08.2016)
AMEO 1.5 L TDi (06.2016 – TILL NOW)
POLO 2'ND GEN 1.5 L TDi (07.2014- 08.2019)
VENTO 2'ND GEN 1.5 L TDi (09.2014- TILL NOW)

ZF PART NO	PRODUCT	OE REF. NUMBER	IMAGE
3000 954 538 MRP: 6957	Clutch Kit	03L141025R 03L141032E	
314 717 MRP: 7133	Front Shock Absorber Suspension Strut Twin-Tube Gas Pressure	6C0 413 031 AN	
317 336 MRP: 4826	Rear Shock Absorber Monotube Gas Pressure Top pin, Bottom Eye	6C0 513 025 AH	




FOR REPAIR OF SKODA/VW

OCTAVIA (1U2) 1.9L DIESEL (09.2002 - 12.2010)

OCTAVIA (1U5) 1.9L DIESEL (07.1998 - 03.2010)

POLO 1.6L TDI (06.2009 -09.2013)

ZF PART NO	PRODUCT	OE REF. NUMBER	IMAGE
3000 845 701 MRP: 13411	Clutch Kit	038 198 141 P 038 198 141 PX	

FOR REPAIR OF SKODA/VW


OCTAVIA (1U2) 1.8L PETROL (05.2001 - 01.2006)

OCTAVIA (1U2) 1.9L DIESEL (09.2002 - 12.2010)

OCTAVIA (1U5) 1.8L PETROL (07.1998 - 03.2010)



OCTAVIA (1U5) 1.9L DIESEL (07.1998 - 03.2010)

POLO 1.6L TDI (06.2009 -09.2013)



ZF PART NO	PRODUCT	OE REF. NUMBER	IMAGE
3000 951 790 MRP: 34812	Clutch Kit	LUK-600000600	



FOR REPAIR OF HYUNDAI
CRETA 1.4L CRDi DIESEL (06.2015-TILL NOW)
ELITE I20 1.4L CRDi DIESEL (08.2014 – TILL NOW)
VERNA FLUIDIC 1.4L CRDi DIESEL (01.2011- 08.2017)

ZF PART NO	PRODUCT	OE REF. NUMBER	IMAGE
3000 954 539 MRP: 7891	Clutch Kit	41300-32001 41100-32021	
3151 654 318 MRP: 801	Release Bearing	4142102000	



FOR REPAIR OF HYUNDAI
i10 1'ST GEN 1.1L PETROL (09.2007-10.2010)
i10 1'ST GEN F/L 1.1L PETROL (08.2010-08.2013)
SANTRO 1'ST GEN 1.0L PETROL (09.1998-05.2003)
SANTRO 1'ST GEN 1.1L PETROL (03.2002-05.2003)
SANTRO XING 2'ND GEN 1.1L PETROL (05.2003-10.2014)

ZF PART NO	PRODUCT	OE REF. NUMBER	IMAGE
3000 954 507 MRP: 2472	Clutch Kit	41300-02520 41100-02520	
3151 654 318 MRP: 801	Release Bearing	4142102000	



FOR REPAIR OF HYUNDAI

GRAND i10 1.2L PETROL (08.2013-11.2016)
GRAND i10 F/L 1.2L PETROL (12.2016-TILL NOW)
XCENT 1.2L PETROL (08.2013-11.2016)
XCENT F/L 1.2L PETROL (12.2016-TILL NOW)

ZF PART NO	PRODUCT	OE REF. NUMBER	IMAGE
3000 954 556 MRP: 4006	Clutch Kit	41300-02850 41100-02850	
3151 654 318 MRP: 801	Release Bearing	4142102000	

FOR REPAIR OF HYUNDAI



CRETA 1.6L PETROL (06.2015-TILL NOW)

ZF PART NO	PRODUCT	OE REF. NUMBER	IMAGE
3000 954 569 MRP:7877	Clutch Kit	41300-26350 41100-26350	
318 578/579 MRP: 3481	Shock Absorber Front Left / Right	54651-A0100	
318 580 MRP: 1970	Shock Absorber Rear Left / Right	55310-A0000	





FOR REPAIR OF HYUNDAI

SANTA FE (CM) 2'ND GEN 2.2L CRDi (01.2009-08.2012)
SANTA FE (CM) 2'ND GEN 2.2L CRDi (06.2011-09.2013)
SANTA FE (DM) 3'RD GEN 2.2L CRDi (12.2013-TILL NOW)

ZF PART NO	PRODUCT	OE REF. NUMBER	IMAGE
3000 970 107 MRP: 22276	Clutch Kit	41200-3B400	
2294 001 057 MRP: 73317	Flywheel Dual-mass flywheel	23200-2F110	

FOR REPAIR OF RENAULT / NISSAN


DUSTER 1.5L HSM3 DIESEL (K9K-886) {01.2012 - 06.2017}
DUSTER 1.5L HSAF DIESEL (K9K-856; K9K-858) { 01.2012 - 06.2017}
TERRANO 5DR 1.5L (DIESEL) (09.2013-NOW)
FLUENCE 1.5L L30B DIESEL (K9K-832) {01.2011 - 12.2014}
FLUENCE 1.5L L333 DIESEL (K9K-826) {01.2015 – TILL NOW}

ZF PART NO	PRODUCT	OE REF. NUMBER	IMAGE
3000 950 538 MRP: 9615	Clutch Kit (6 Speed Transmission)	302057505R	
3182 654 278 MRP: 3330	CSC – Central Slave Cylinder Clutch (6 Speed Transmission)	23200-2F110	





FOR REPAIR OF RENAULT / NISSAN

DUSTER 1.5L HSM3 DIESEL (K9K-886) {01.2012 - 06.2017}
DUSTER 1.5L HSAF DIESEL (K9K-856; K9K-858) { 01.2012 - 06.2017}
TERRANO 5DR 1.5L (DIESEL) (09.2013-NOW)
FLUENCE 1.5L L30B DIESEL (K9K-832) {01.2011 - 12.2014}
FLUENCE 1.5L L333 DIESEL (K9K-826) {01.2015 – TILL NOW}

ZF PART NO	PRODUCT	OE REF. NUMBER	IMAGE
2294 002 113 MRP: 30932	Flywheel Dual-mass flywheel (6 Speed Transmission)	123006354R	

FOR REPAIR OF RENAULT / NISSAN

DUSTER 1.5L HSMW DIESEL (K9K-796/KNK-830) {01.2012 - 06.2017}
LODGY 1.5L JSMW DIESEL (KNK-830){04.2015 - 09.2019}
PULSE 1.5L BDMD DIESEL (K9K-422) {1.2012 - TILL NOW}
SCALA 1.5L LJMD DIESEL (K9K-422) {01.2012 - 09.2019}
EVALIA 1.5L DIESEL (K9K) {08.2012 - TILL NOW}
EVALIA 1.5L DIESEL (K9K) {04.2015 - TILL NOW}
MICRA (K13K) 1.5L DIESEL {05.2010 - 04.2013}
MICRA F/L (K13K) 1.5L DIESEL {04.2013 - 06.2017}
SUNNY (N17K) 1.5L DIESEL {09.2011 - 04.2014}
SUNNY (N17KK) 1.5L DIESEL{04.2014 - TILL NOW}
TERRANO 1.5 L DIESEL (09.2013 - 05.2020)

ZF PART NO	PRODUCT	OE REF. NUMBER	IMAGE
3000 954 540 MRP: 9432	Clutch Kit (5 Speed Transmission)	8200527569 8200335084	
3182 654 204 MRP: 3288	CSC – Central Slave Cylinder Clutch (5 Speed Transmission)	510009010	



FOR REPAIR OF RENAULT/NISSAN

DUSTER 1ST GEN 1.6L HSA8 (TYPE 1) PETROL K4M-690; K4M-606 (01.2012 - 02.2015)

DUSTER 1ST GEN 1.5L HSM3 (TYPE 1) DIESEL K9K-886 (01.2012 - 02.2015)



DUSTER 1ST GEN 1.5L HSMW (TYPE 1) DIESEL K9K-796; K9K-830 (01.2012 - 02.2015)

DUSTER 1ST GEN 1.5L HSAF (TYPE 1) DIESEL K9K-856; K9K-858 (01.2012 - 02.2015)

TERRANO 1.5L XE / XL PLUS DIESEL K9K-796; K9K-830 (09.2013 – NOW)



TERRANO 1.5L XV PREMIUM DIESEL K9K-886 (09.2013 – NOW)

TERRANO 1.6L XL PETROL K4M-690; K4M-606 (09.2013 – NOW)



ZF PART NO	PRODUCT	OE REF. NUMBER	IMAGE
318 581 MRP: 2998	Front Suspension Strut Element Left/ Right	543026656R 8200813791 543029162R 543026656R	
318 582 MRP: 2683	Rear Shock Absorber	562105043R 562106996R	



FOR REPAIR OF HONDA
CITY 4'TH GEN 1.5L PETROL (09.2003-10.2009)

ZF PART NO	PRODUCT	OE REF. NUMBER	IMAGE
3000 954 525 MRP: 4677	Clutch Kit	22300-PWA-005 22200-PWC-005	
3151 654 327 MRP: 821	Release Bearing	22810PLW005	



FOR REPAIR OF HONDA
CITY 5'TH GEN 1.5L PETROL (01.2009-01.2013)
CITY 6'TH GEN 1.5L PETROL (01.2014-03.2017)
CITY 6'TH GEN F/L 1.5L PETROL (03.2017-TILL NOW)
AMAZE 1'ST GEN 1.2L PETROL,CNG (04.2013-03.2016)
AMAZE 1'ST GEN F/L 1.2L PETROL,CNG (03.2016-05.2018)
BR-V 1.5L PETROL (05.2016-TILL NOW)
BRIO 1'ST GEN 1.2L PETROL (01.2011-10.2016)
BRIO 1'ST GEN F/L 1.2L PETROL (10.2016-TILL NOW)
JAZZ 1'ST GEN 1.2L PETROL (06.2009-08.2012)
JAZZ 1'ST GEN F/L 1.2L PETROL (01.2012-12.2013)
JAZZ 2'ND GEN 1.2L PETROL (07.2015-TILL NOW)
MOBILIO 1.5L PETROL (07.2014-06.2017)
WR-V 1.2L PETROL (03.2017-TILL NOW)

ZF PART NO	PRODUCT	OE REF. NUMBER	IMAGE
3000 954 524 MRP: 4413	Clutch Kit	22300-RB0-005 22200-RB0-005	
3151 654 327 MRP: 821	Release Bearing	22810PLW005	




FOR REPAIR OF HONDA

CITY 6'TH GEN 1.5L DIESEL (01.2014-03.2017)
 CITY 6'TH GEN F/L 1.5L DIESEL (03.2017-TILL NOW)
 AMAZE 1'ST GEN 1.5L DIESEL TURBO (04.2013-03.2016)
 AMAZE 1'ST GEN F/L 1.5L DIESEL (03.2016-05.2018)
 BR-V 1.5L DIESEL (05.2016-TILL NOW)
 BRIO 1'ST GEN 1.5L DIESEL (01.2011-10.2016)
 BRIO 1'ST GEN F/L 1.5L DIESEL (10.2016-TILL NOW)
 JAZZ 2'ND GEN 1.5L DIESEL (11.2016-TILL NOW)
 MOBILIO 1.5L DIESEL (07.2014-06.2017)
 WR-V 1.5L DIESEL (03.2017-TILL NOW)

ZF PART NO	PRODUCT	OE REF. NUMBER	IMAGE
3000 954 541 MRP: 5613	Clutch Kit	2230059M003 2220059M003	
3151 654 322 MRP: 851	Release Bearing	22810PPT003	

FOR REPAIR OF HONDA



CRV MK 3'RD GEN 2.0 L RVI PETROL (10.2007-12.2011)
 CRV MK 3'RD GEN 2.4 L RVI PETROL (10.2007-12.2011)
 CRV RE 4'TH GEN 2.0 L RVI-1 PETROL (01.2013-11.2016)

ZF PART NO	PRODUCT	OE REF. NUMBER	IMAGE
3000 954 586 MRP: 7484	Clutch Kit	22300R6V015 22200R6V005	



FOR REPAIR OF TOYOTA MOTORS

FORTUNER 1ST GEN 3.0 SR 4WD DIESEL (08.2009 - 12.2011)
FORTUNER 1ST GEN F/L 3.0 SR 2WD DIESEL MT (01.2012 - 11.2016)

ZF PART NO	PRODUCT	OE REF. NUMBER	IMAGE
3000 954 523 MRP: 11048	Clutch Kit	31210-0K190 31250-0K222	
3151 654 323 MRP: 1161	Release Bearing	3123071011	


FOR REPAIR OF TOYOTA MOTORS

INNOVA 1ST GEN 2.5 DLX BSIII DIESEL (02.2005 - 01.2012)
INNOVA 1ST GEN 2.5 DLX BSIV DIESEL (04.2010 - 01.2012)
INNOVA 1ST GEN 2.5 GL BSIII DIESEL (02.2005 - 01.2012)
INNOVA 1ST GEN 2.5 GL BSIV DIESEL (04.2010 - 01.2012)
INNOVA 1ST GEN 2.5 STD BSIII DIESEL (02.2005 - 01.2012)
INNOVA 1ST GEN 2.5 STD BSIV DIESEL (04.2010 - 01.2012)
INNOVA 1ST GEN F/L 2.5 DLX DIESEL (01.2012 - 03.2016)
INNOVA 1ST GEN F/L 2.5 GL DIESEL (01.2012 - 03.2016)
INNOVA 1ST GEN F/L 2.5 STD DIESEL (01.2012 - 03.2016)


ZF PART NO	PRODUCT	OE REF. NUMBER	IMAGE
3000 954 537 MRP: 5859	Clutch Kit	31210-0K030 31250-0K040	
3151 654 321 MRP: 1041	Release Bearing	3123071030	



FOR REPAIR OF TOYOTA MOTORS
 ETIOS 1.4 G DIESEL (08.2011 - 09.2016)
 ETIOS 1.4 STD DIESEL (08.2011 - 09.2016)
 ETIOS 1.4 V DIESEL (08.2011 - 09.2016)
 ETIOS CROSS 1.4 SUV V DIESEL (04.2014 – TILL NOW)
 ETIOS CROSS 1.4 SUV G DIESEL (04.2014 – TILL NOW)
 ETIOS LIVA 1.4 G DIESEL (06.2011 – TILL NOW)
 ETIOS LIVA 1.4 STD DIESEL (03.2013 – TILL NOW)
 ETIOS LIVA 1.4 V DIESEL (03.2013 – TILL NOW)

ZF PART NO	PRODUCT	OE REF. NUMBER	IMAGE
3000 954 542 MRP: 6288	Clutch Kit	31210-52140 31250-52271	


FOR REPAIR OF TOYOTA MOTORS
 ETIOSS (1.5G) - PETROL (12.2010-09.2016)
 ETIOSS (1.5 STD) - PETROL (12.2010-09.2016)
 ETIOSS (1.5V) - PETROL (12.2010-09.2016)
 ETIOSS CROSS 1.2 SUV G - PETROL (04.2014-NOW)
 ETIOSS CROSS 1.2 SUV V - PETROL (04.2014-NOW)
 ETIOSS LIVA (1.2G) - PETROL (06.2011-NOW)
 ETIOSS LIVA (1.2 V) - PETROL (06.2011-NOW)
 ETIOSS LIVA TRD SPORTIVO (1.5G) – PETROL (03.2013-09.2016)

ZF PART NO	PRODUCT	OE REF. NUMBER	IMAGE
3000 954 578 MRP:5229	Clutch Kit	312100D140 312500D151	





FOR REPAIR OF MAHINDRA

KUV 100 1.2L K6 5S DIESEL (01.2016 - 10.2017)
 KUV 100 1.2L K6 6S DIESEL (01.2016 - 10.2017)
 KUV 100 1.2L K6+ 5S DIESEL (01.2016 - 10.2017)
 KUV 100 1.2L K6+ 6S DIESEL (01.2016 - 10.2017)
 KUV 100 1.2L K8 5S DIESEL (01.2016 - 10.2017)
 KUV 100 1.2L K8 6S DIESEL (01.2016 - 10.2017)
 KUV 100 F/L 1.2L K6+5S DIESEL (10.2017 – TILL NOW)
 KUV 100 F/L 1.2L K6+6S DIESEL (10.2017 – TILL NOW)
 KUV 100 F/L 1.2L K8 5S DIESEL (10.2017 – TILL NOW)
 KUV 100 F/L 1.2L K8 6S DIESEL (10.2017 – TILL NOW)

ZF PART NO	PRODUCT	OE REF. NUMBER	IMAGE
3000 950 092 MRP: 6207	Clutch Kit	0801CAA0005KT	

FOR REPAIR OF MAHINDRA


TUV 300 1.5L T4/T6/T10 REFRESH DIESEL (01.2019-TILL NOW)
 TUV 300 1.5L T10 DIESEL(09.2017-TILL NOW)
 TUV 300 1.5L T4 DIESEL (09.2015-TILL NOW)
 TUV 300 1.5L T6 DIESEL (09.2015-TILL NOW)
 TUV 300 1.5L T8 (09.2015-TILL NOW)
 NUVOSPORT 1.5L N4 DIESEL(04.2016-TILL NOW)
 NUVOSPORT 1.5L N6 DIESEL (04.2016-TILL NOW)
 NUVOSPORT 1.5L N8 DIESEL (04.2016-TILL NOW)
 BOLERO 2ND GEN 1.5L POWER+ LX DIESEL (09.2016-TILL NOW)
 BOLERO 2ND GEN 1.5L POWER+ SLE DIESEL (09.2016-TILL NOW)
 BOLERO 2ND GEN 1.5L POWER+ SLX DIESEL (09.2016-TILL NOW)
 BOLERO 2ND GEN 1.5L POWER+ ZLX DIESEL (09.2016-TILL NOW)

ZF PART NO	PRODUCT	OE REF. NUMBER	IMAGE
3000 950 094 MRP: 5071	Clutch Kit	0801BAA0003KT	
2294 002 361 MRP: 18808	Dual Mass Flywheel	0312CAM00851N	





FOR REPAIR OF MAHINDRA

SCORPIO 1ST GEN F/L 2.2L - mHAWK DIESEL (04.2006 - 03.2008)
SCORPIO 2'ND GEN 2.2L SLE - mHAWK DIESEL (04.2008-09.2014)
SCORPIO 2'ND GEN 2.2L VLX - mHAWK DIESEL (04.2008-09.2014)
SCORPIO GATEWAY SC 2.2L - mHAWK DIESEL (04.2014-NOW)

ZF PART NO	PRODUCT	OE REF. NUMBER	IMAGE
3000 954 579 MRP: 7165	Clutch Kit	0801CA0341N 0801BA0841N	



FOR REPAIR OF MAHINDRA & MAHINDRA

MARAZZO 1.5L DIESEL (09.2018-NOW)
XUV 300 1.5L DIESEL (02.2019-NOW)


ZF PART NO	PRODUCT	OE REF. NUMBER	IMAGE
3000 954 559 MRP: 6613	Clutch Kit	0801CAA01311N 0801BAA01631N 0801CAA0012KT	
2294 002 379 MRP: 17762	Dual Mass Flywheel	0312CBF00041N	



FOR REPAIR OF MAHINDRA & MAHINDRA
XUV 300 1.2L PETROL W4/W6/W8 (02.2019-NOW)
XUV 300 1.2L PETROL W4/W6/W8 BS6 (01.2020-NOW)

ZF PART NO	PRODUCT	OE REF. NUMBER	IMAGE
3000 954 606 MRP:	Clutch Kit	0801CAA01381N 0801BAA01881N	
2294 002 473 MRP:	Dual Mass Flywheel	0312CAW00441N	



FOR REPAIR OF MARUTI SUZUKI
SWIFT 2ND GEN (TYPE-1/2/3) - PETROL (08.2011-01.2016)
RITZ 2ND GEN (TYPE-2) - PETROL (07.2012-02.2017)
DZIRE 2ND GEN (TYPE-1/2/3) - PETROL (02.2012-02.2017)

ZF PART NO	PRODUCT	OE REF. NUMBER	IMAGE
3000 954 577 MRP: 3702	Clutch Kit	22100M83K40 22400M83K02	





FOR REPAIR OF FORD

ECOSPORT 1.5L DIESEL 1.5DV5 ENGINE (06.2013-11.2017)
ECOSPORT 1.5L DIESEL 1.5DV5 ENGINE (11.2017-05.2019)
FIESTA 2'ND GEN 1.5L DIESEL 1.5DURATORQ ENGINE (09.2011-06.2014)
FIESTA 2'ND GEN F/L 1.5L DIESEL 1.5DURATORQ ENGINE (06.2014-09.2015)
FORD FIGO 2ND GEN 1.5L DIESEL (08.2015- TILL NOW)

ZF PART NO	PRODUCT	OE REF. NUMBER	IMAGE
3000 954 555 MRP: 4274	Clutch Kit	8V217540DE 8V217540DF 8V2Z7B546D	
3182 654 279 MRP: 2295	CSC – Central Slave Cylinder Clutch	1547820	




FOR REPAIR OF FORD

ECOSPORT 1.5L PETROL 1.5Ti-VCT ENGINE (06.2013-11.2017)
FORD FIGO 2ND GEN 1.5L PETROL DURATEC (09.2011- 06.2014)



ZF PART NO	PRODUCT	OE REF. NUMBER	IMAGE
3000 954 091 MRP: 6391	Clutch Kit	BV217540E1A BV217540E9A	
3182 654 279 MRP: 2295	CSC – Central Slave Cylinder Clutch	1547820	



FOR REPAIR OF FORD
ECOSPORT 1.5L DIESEL 1.5DV5 ENGINE (06.2013-11.2017)
ECOSPORT 1.5L DIESEL 1.5DV5 ENGINE (11.2017-05.2019)
ECOSPORT 1.5L PETROL 1.5Ti-VCT ENGINE (06.2013-11.2017)


ZF PART NO	PRODUCT	OE REF. NUMBER	IMAGE
318 574 MRP: 3368	Front Suspension Strut Element Left	FN1C18K001AB DN1C18K001AD M2N3G8269	
318 575 MRP: 3368	Front Suspension Strut Element Right	DN1C18045AD FN1C18045AB M2N3G8268	
318 576 MRP: 2117	Rear Shock Absorber	DN1C18097AB FN1C18080AB M2N3G2505	

FOR REPAIR OF FORD
ECOSPORT 1L PETROL ECOBOOST ENGINE (06.2013 - 11.2017)


ZF PART NO	PRODUCT	OE REF. NUMBER	IMAGE
3000 950 075 MRP:	Clutch Kit	1843122 1760705 C1BG7540CD	
3182 654 279 MRP: 2295	CSC – Central Slave Cylinder Clutch	1547820	



**FOR REPAIR OF ASHOK LEYLAND
DOST 1.5L DIESEL (09.2011-NOW) – 1.25 TONNER**


ZF PART NO	PRODUCT	OE REF. NUMBER	IMAGE
3000 954 567 MRP: 3718	Clutch Kit (Dia.215 mm)	ASHOK LEYLAND - 010220G6300 LUK - 1622G6300 VALEO - 404578	

**FOR REPAIR OF MITSUBISHI
PAJERO SPORT 2.5L DIESEL (03.2012 – TILL NOW)**

ZF PART NO	PRODUCT	OE REF. NUMBER	IMAGE
3000 954 587 MRP: 12800	Clutch Kit	MBC659-EXCEDY MBD129U-EXCEDY	



AFTERMARKET



CLUTCHES

SACHS SHOCK ABSORBERS.

OE QUALITY.

RIGOROUSLY TESTED.



PROVEN PERFORMANCE

